


# Building an inexpensive airbrush over-spray booth.



**Y**ou can begin using your Norvell Sunless Spray System immediately and protect your working area from over-spray by building a over-spray area using a few inexpensive items available from a your local retail stores.

1. Select a well lighted corner of your business or unused room.
2. Hang a regular size, smooth plastic shower curtain against the wall. Place the curtain so that the bottom of the curtain to touches the floor. Curtains with weights sewn in the bottom corners work best.
3. Purchase a square remnant of indoor-outdoor carpet (low knap) or rug of choice, to place in the corner for the customer to stand on. A piece about 5 feet square will work well. For hygiene, place a new small towel on the carpet for each customer.
4. Set up a 24 inch box fan, available from local Lowes or Walmart for less than \$15 dollars. Place a 24" filter you would use in a return air vent in your home heating system. Place the filter on the intake side of the fan. The air-flow into the fan will hold the filter against the fan. Two fans will work even better. There are fans available commercially with a filter attached to them when you buy it. (These are now available from Norvell Sunless.)
5. Place the fans a few feet (6-7 feet) from the corner. Set the fans so that they blow AWAY from the customer and the spray area. This will filter any of the over-spray that does not hit the curtain or drop to the floor.



**NORVELL**  
BodyInvest

For more Information call 888.829.2831

© 2003 BodyInvest, LLC. part 04-008